

Amendments to the Drawings

The attached sheet of drawings includes changes to Figure 1. This sheet, which includes Figure 1, replaces the original sheet including Figure 1. In amended Figure 1, a reference number 30 depicting a diagnostic output signal having an associated lead line has been added as disclosed in Pending Application, page 11, line 20, and the word "OUTPUT" has been removed. Additionally, a positive feed back assembly having associated reference number "32" and lead line has been added as disclosed in Pending Application, page 11, lines 21-22. Also, both a selectively energizable light assembly having an associated reference number "34" and lead line has been added as disclosed in Pending Application, page 12, lines 3-4; and a selectively energizable audio assembly having an associated reference number "36" and lead line has been added as disclosed in Pending Application, page 12, lines 4-5.

Attachment: Replacement Sheet  
Annotated Sheet Showing Changes



APR 02 2004

四

## Annotated Sheet

Inventor: David Crist Gabriel

Serial No.: 10/063 868

## For: Diagnostic Method for an Electric Drive Assembly

BEST AVAILABLE COPY




Figure 1



BEST AVAILABLE COPY

## Replacement Sheet

For: **Diagnostic Method for an Electric Drive Assembly**  
Inventor: **David Crist Gabriel**  
Serial No.: **10/063,868**




Figure 1